

VEHICLE INSPECTION REPORT

SG13WHA

Peugeot Bipper 1.3 HDi 75PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 27/03/2013

Year 2013

Mileage 59,484 Miles Not Warranted

Fuel Type DIESEL

GVW 1750kg

Colour BLUE

VIN VF3AAFHZ0D8375470

Body Style Panel Van SWB

MOT Due 25/01/2027

CAP Clean £700.00

CAP Average £530.00

CAP Below £350.00

Gearbox MANUAL

Gears 5

Axle Combi 4x2

POSSIBLE INPUT ERROR IN MOT HISTORY

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Rear parking sensor

Photos





Condition Check



Damage Photos



1: Carpets Front
Missing
Replace

2: Sill os
Rusted
Over 5mm



3: Bonnet
Dented
Over 30mm

4: Wing osf
Rusted
Over 5mm



5: Door osf
Dented
With Paint Damage

6: Qtr Panel osr
Dented
Over 2 UpTo 10mm



7: Tailgate
Dented
Over 30mm

8: Door nsr
Dented
With Paint Damage



9: Sill ns
Dented
With Paint Damage

10: Door nsf
Dented
Over 30mm



11: Wing nsf
Rusted
Over 5mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK