

# VEHICLE INSPECTION REPORT

**PK67VGN**

## Daf CF 450

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 09/11/2017

Year 2017

Mileage 1,466,522 Km  
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G181526

Body Style Tractor Unit

Service history Yes

MOT Due 31/03/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

\*WARNING LIGHT ON DASH\*

### Tyres

NSF

NSI1

NSI2

NSI3

NSI4

OSF

OSI1

OSI2

OSI3

OSI4

Spare

NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3






OSO4

## Features

- Cruise control
- Central locking
- Radio/CD
- Cloth seat trim
- Air conditioning
- Front electric windows


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips

2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Door Mirror Assy nsf  
Broken  
Replace

4: Wing nsf  
Cracked  
Replace



5: Door nsf  
Dented  
Over 30mm

6: Door Mirror Assy osf  
Broken  
Replace



7: Door osf  
Scratched  
Over 25mm Not Thru Paint

8: Screen Front  
Chipped  
Over 10mm



9: Door Pad osf  
Broken  
Replace

10: Seat Base Cover nsf  
Holed  
Over 3mm

**Interior**

|                         |      |                             |      |
|-------------------------|------|-----------------------------|------|
| <b>Carpet Condition</b> | OK   | <b>Upholstery Condition</b> | Poor |
| <b>Seat Condition</b>   | Poor | <b>Odour</b>                | -    |
| Engine Runs             | OK   | No Excessive Smoking        | OK   |
| EML light illuminated   | OK   | DPF light illuminated       | OK   |
| ABS light illuminated   | OK   |                             |      |