

VEHICLE INSPECTION REPORT

LO69LNW

Ford Ranger XLT 2.0 EcoBlue 170PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 To Follow
Cap Id 44058
Cap Code FORA20XLT 7DTM4 6
L

Details

Location	Doncaster	Colour	WHITE	CAP Below	£3,750.00
Reg. date	31/12/2019	VIN	6FPPXXMJ2PKT42514	Gearbox	MANUAL
Year	2019	Body Style	Pickup Double Cab	Gears	6
Mileage	131,552 Miles Warranted	MOT Due	19/10/2026	Axle Combi	4x4
Fuel Type	DIESEL	CAP Clean	£5,625.00		
GVW	3270kg	CAP Average	£4,825.00		

WARNING LIGHTS ON DASH E/MIRRORS, AD-BLUE

Tyres

NSF

NSR

OSF

OSR



Spare

Features

- Bluetooth connection
- Air conditioning
- Passenger airbag
- Cruise control
- Front electric windows
- Central locking
- Auxiliary input socket
- Rear electric windows
- Cloth seat trim
- Digital radio
- Drivers airbag


Photos








Condition Check



Damage Photos



1: Wing osf
Chipped
Multiple Chips

2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Chipped
Multiple Chips

4: Door nsr
Chipped
Multiple Chips



5: Qtr Panel nsr
Chipped
Multiple Chips



6: Tailgate
Dented
With Paint Damage



7: Qtr Panel osr
Dented
Over 30mm

8: Qtr Panel osr
Scratched
Over 25mm Thru Paint





9: Qtr Panel osr
Chipped
Multiple Chips

10: Sill os
Rusted
Over 5mm



11: Seat Base Cover osr
Soiled
Heavy

12: Door Pad osf
Soiled
Heavy



13: Seat Base Cover osf
Holed
Over 3mm

14: Seat Back Cover osf
Soiled
Heavy



15: Seat Base Cover nsf
Soiled
Heavy

16: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
OK		Poor	
Poor		No	
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	OK		